

# 278 CLEVEDON-KAWAKAWA ROAD

Prepared for Stratford Properties Ltd

Preliminary Site Investigation

April 2020

# **REPORT INFORMATION AND QUALITY CONTROL**

Prepared for:

Stratford Properties Ltd

Author:	Shannen Barns	
	Environmental Consultant	at l
Reviewer:	James Blackwell CEnvP (No. SC41083)	h
	Principal Land and Water Quality Consultant	Alexand
Approved for Release:	Nigel Mather	lhalt
Neicase.	Principal Land and Water Quality Consultant	MINLAD

Document Name	R_AA4755 278 Clevedon-Kawakawa Rd P	SI_v5.0 (March 2020)
Version History:	1.0	May 2019
	2.0	June 2019
	3.0	October 2019
	4.0	March 2020
	5.0	April 2020









## **CONTENTS**

## Page

SUIT	ABLY C	QUALIFIED AND EXPERIENCED PRACTITIONER (SQEP) STATEMENT OF QUALIFICATIONS	. 1
EXEC		SUMMARY	. 2
1	INTRO	DUCTION	. 4
	1.1	Scope of Works	4
2	SITE D	ETAILS	. 4
	2.1	Geology	7
3	SITE H	ISTORY	
	3.1	Council Records	7
	3.1.1	Property File Review	7
	3.1.2	Site Contamination Enquiry	8
	3.1.3	Contaminated Land Database and Closed Landfill Search	8
	3.1.4	Hazardous Substances and Incidents Report	8
	3.2	Historical Aerial Photographs	
	3.3	Landowner Information	10
4	SITE IN	NVESTIGATION	
	4.1	Site Walkover	10
5	CONC	LUSIONS	
REFE	RENCE	S	13
LIMI	ΤΑΤΙΟΙ	VS	13

## **List of Tables**

Table 1: Address and Site Information	. 7
Table 2: Aerial Photograph Review	. 9

## **List of Figures**

Figure 1: Site Location Plan	. 6
•	

# **List of Appendices**

Appendix A: Preliminary Development Plans Appendix B: Property File Appendix C: Site Contamination Enquiry Appendix D: Contaminated Land Database and Closed Landfil Search Appendix E: Historical Aerial Photographs Appendix F: Photolog



# SUITABLY QUALIFIED AND EXPERIENCED PRACTITIONER (SQEP) STATEMENT OF QUALIFICATIONS

James Blackwell CEnvP SC (Reviewer):	James is an EIANZ Certified Environmental Practitioner – Site Contamination specialist (CEnvP SC), and a Principal Land & Water Quality Consultant with 13 years environmental consultancy experience, specialising in contaminated land assessment, management and remediation of a range of contaminants in soil, groundwater and as soil vapour.
	He has a broad range of experience in contaminated land management, including; landfill monitoring, assessment and redevelopment; environmental due diligence; hydrogeological investigation; air pollution modelling and control; environmental impact assessment; and human health and environmental risk assessment.
Nigel Mather (Approver):	Nigel is a Principal Land and Water Quality Consultant and has been an environment and health and safety professional for 16 years. He has a broad range of environmental management and risk assessment experience, including contaminated land assessment and remediation, environmental due diligence and risk assessment (transactional and advisory services), and HSE management systems implementation and auditing.



# **EXECUTIVE SUMMARY**

4Sight Consulting Ltd (4Sight) has been engaged by Stratford Properties Ltd ('the client') to undertake a Preliminary Site Investigation (PSI) at 278 Clevedon-Kawakawa Road, Clevedon (herein referred to as 'the site'). This investigation included reviewing the site's history and field observations.

The key findings of this PSI are:

- The site occupies an area of approximately 520,000 m<sup>2</sup> of rural land of relatively level topography in Clevedon in the Auckland region and is currently subject to a Private Plan Change for re-zoning from Rural Coastal to Rural Countryside Living under the Auckland Unitary Plan: Operative in Part (AUP: OP). Given the limited countryside living development opportunities at the site due to the extent of flooding constraints, and the nature of the clustered countryside living subdivision and development that is provided for by the Rural Countryside Living Zone and the Clevedon Sub Precinct C provisions, only a portion of the site is proposed to be redeveloped;
- The portion of the site proposed for Rural-Countryside Living includes a naturally raised area of land (approximately 41,060 m<sup>2</sup>) as well as a relatively level area (approximately 13,550 m<sup>2</sup>) in the south-western portion of the site (collectively the 'Piece of Land'). The remaining area of the site will continue to be in use as rural production land;
- During site visits by 4Sight staff, no buildings or structures and no visible signs of contamination were identified within the Piece of Land;
- A review of historical aerial images identified the site has been in use as rural land in pasture, comprised of multiple paddocks from at least the 1960's present. Small, singular farm buildings have been present on the site's western boundary and south-eastern corner during this time. There has been no evidence of significant land disturbance or presence of structures within the Piece of Land during this time;
- Several small-scale farm sheds are present in the western portion of the site, outside of the Piece of Land, constructed of corrugated iron and timber, with the cladding of one shed constructed of potential ACM in deteriorating condition. It is noted that the Private Plan Change will include the amalgamation of the area in which these sheds are located with the neighbouring property; and
- Property files and a Site Contamination Enquiry obtained from AC, as well as a search of the AC Contaminated Land and Closed Landfills Databases did not identify any potentially contaminating activities that are currently or have historically occurred on the site (including the Piece of Land). No hazardous substances incidences have occurred on the site or any surrounding properties according to a review of information maintained by the Environmental Protection Agency (EPA).

## Based on the findings of this investigation the following recommendations have been made:

- Based on observations during the site visit and review of background material, it is considered there is no record
  of HAIL activities that are currently or have previously been undertaken on the Piece of Land. In addition, the
  remainder of the site will continue to be used as production land. On this basis, the NESCS is not applicable to the
  proposed subdivision, change of land use and soil disturbance associated with the residential development of the
  site;
- Soils within the Piece of Land have not been subject to HAIL activities, and as such it is considered highly unlikely that contaminants in soil would pose a risk to human health. If soils are to be excavated they are suitable for reuse on the site from a human health risk perspective. If soils are to be disposed of off-site, they would likely be considered as cleanfill, however this should be confirmed through analysis and confirmation with the disposal facility prior to removal from the site; and
- There is the potential for asbestos in shallow soils associated with the use of asbestos containing building materials in buildings at the site, outside of the Piece of Land. The NESCS is not applicable to the remainder of the site, outside of the Piece of Land, as long as it continues to be in use as production land. However, should removal of this building be required, an asbestos survey of the building should be undertaken and, should ACM be confirmed, the removal/demolition should be managed in accordance with the Health and Safety at Work (Asbestos) Regulations 2016, and the WorkSafe New Zealand Approved Code of Practice for the Management and Removal of Asbestos.



 This investigation and associated reporting have been carried out, supervised and revised by suitably qualified and experienced practitioners (SQEP) in accordance with the NESCS.



# **1** INTRODUCTION

4Sight Consulting Ltd (4Sight) has been engaged by Stratford Properties Ltd (or 'the client') to undertake a Preliminary Site Investigation (PSI) at 278 Clevedon-Kawakawa Road, Clevedon (herein referred to as 'the site').

The site is currently subject to a Private Plan Change to be re-zoned from Rural Coastal to Rural Countryside Living under the Auckland Unitary Plan: Operative in Part (AUP: OP). Given the limited countryside living development opportunities at the site due to the extent of flooding constraints, only a portion of the site (the Piece of Land) is proposed to be redeveloped.

The purpose of this investigation is to determine whether activities listed on the Ministry for the Environment (MfE) Hazardous Activities and Industries List (HAIL) have historically been or are currently being undertaken on the site.

Consideration of the National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health (NESCS) is required for the activities of subdivision on pieces of land that have been subject to any activities or industries listed on the HAIL. Specifically, land covered in the NESCS is defined in regulation 5(7) as:

A piece of land that is described by one of the following:

- a) An activity or industry described in the HAIL is being undertaken on it;
- b) An activity or industry described in the HAIL has been undertaken on it;
- c) It is more likely than not that an activity or industry described in the HAIL is being or has been undertaken on it.

# 1.1 Scope of Works

The purpose of this PSI is to first confirm the nature and extent of historic activities at the site, determine the likely presence of potential contamination in shallow soil associated with historic activities undertaken at the site through review of selected publicly available information, and to determine the applicability of the NESCS to the proposed subdivision and change of land use.

The scope of this PSI has included the following:

- A review of selected publicly available information for the site, including council files and aerial photographs to confirm whether or not any activities or industries on the HAIL are, have been, or might have been undertaken on the site;
- Site inspection to visually assess the presence of activities or industries listed on the HAIL or evidence of potential contamination; and
- An overall assessment of the applicability of the NESCS.

# 2 SITE DETAILS

The site is located in Clevedon in the Auckland Region, and details of the site are provided in Table 1 below. The site is zoned as Rural Coastal Zone under the Auckland Unitary Plan: Operative in Part (AUP: OP) and is currently a rural property in pasture with some additions such as farm sheds and stock yards. The site is proposed to undergo a Private Plan Change to be re-zoned to Rural – Countryside Living.

The site is legally described as LOT 1 DP 146882 and comprises an area of approximately 520,000 m<sup>2</sup> of rural land. It is understood that only a portion of the site is subject to the proposed redevelopment, including a raised natural hill area of approximately 41,060 m<sup>2</sup> in the south-western portion of the site and a relatively level area of approximately 13,550 m<sup>2</sup> adjacent to the site's southern boundary (collectively herein referred to as the 'Piece of Land').

The proposed redevelopment, limited to within the Piece of Land, will include the addition of twelve new residential dwellings within the existing Lot (LOT 1 DP 146882) as well as a shared accessway, with access to Clevedon-Kawakawa Road. The remainder of the site will continue to be in use as rural production land. Preliminary plans detailing the proposed redevelopment of the site are presented in Appendix A.



The site location and location of the proposed redevelopment within the site are shown in Figure 1.



Copyright: This document and the copyright in this document remains the property of ASight Consulting. The contents of this document may not be reproduced either in whole or in part by any means without prior consent of 4Sight Consulting



320m

AA4755 - 278 Clevedon-Kawakawa Rd PSI

Figure 1: Site Location Plan

Figure prepared for Stratford Properties Ltd by 4Sight Consulting.

Version: 1.0 Drawn: Sam Hendrikse Checked: Shannen Barns Approved: Nigel Mather





#### Table 1: Address and Site Information

Address		Legal Description	CT Number	Area
278 Clevedon-Kaw Clevedon, Auck	,	LOT 1 DP 146882	NA87C/391	<ul> <li>The site: Approximately 520,000 m<sup>2</sup></li> <li>The Piece of Land: Approximately 54,610 m<sup>2</sup></li> </ul>

# 2.1 Geology

The Institute of Geological and Nuclear Sciences (GNS) 1:250,000 online geological map shows the regional geology consists of two lithologies.

Middle Pleistocene – Late Pleistocene river and hill slope deposits (OIS5+-OIS2) are present along the site's southern boundary, adjacent to Clevedon-Kawakawa Road, and extend to a distance of approximately 200 – 300 m within the site, comprising both the south-western and south-eastern portions of the site. These rocks are described as predominantly pumiceous sand, silt, mud and clay, with interbedded gravel and peat. The remainder of the site is comprised of Holocene River Deposits (OIS1). These rocks are described as sand, silt mud and clay with local gravel and peat beds. The geological contact between these two lithologies runs through southern portion of the site.

The closest surface water body flows through the centre of the site, parallel to the orientation of the site's eastern and western boundaries. The stream is unnamed with a river number of 85050 in the AC Geomaps database. The stream feeds into the Wairoa river directly north of the site, which drains into the Hauraki Gulf near Kauri Bay approximately 4 km north west of the site.

# **3** SITE HISTORY

To understand the history of the site and particularly the nature and location of any potentially contaminating activities, a review of selected publicly available information for the site was undertaken.

This included searches of the following:

- Property File Report provided by Auckland Council (AC);
- Site Contamination Enquiry provided by AC;
- Contaminated Land Database and Closed Landfill searches through AC;
- Hazardous Substances and Incidents Report provided by the Environmental Protection Agency (EPA);
- Selected historic aerial photographs readily available through Retrolens<sup>®</sup>, AC Geomaps and Google Earth Pro<sup>®</sup>; and
- Information obtained by communication with the client, landowner and current users of the site.

## 3.1 Council Records

## 3.1.1 Property File Review

The property file for 278 Clevedon-Kawakawa Road, Clevedon was requested and provided to 4Sight on 1 May 2019 by AC and selected excerpts from the file are provided in Appendix B. The following information of relevance to this investigation was obtained from the file:

 Building Permit (Permit No. J29788), dated November 1991, to erect a relocated dwelling including additions and a new carport at 278 Clevedon-Kawakawa Road, Clevedon (LOT 1 DP 146882).

Review of the property file did not identify records of any potentially contaminating activities that have historically occurred on the site.



## 3.1.2 Site Contamination Enquiry

The Site Contamination Enquiry provides information on records held by AC for landfills, bores, air discharge consents, industrial and trade process consents, contaminated site discharge consents and environmental incidents at the site and within a 200 m radius of the property.

A response from AC was received on 7 May 2019 and is presented in Appendix C. The response identified the following:

- No pollution incident files regarding spills/contamination were found for the above site; and
- The records reviewed as part of the Site Contamination Enquiry search do not identify individual horticultural sites in the region. However, the records state that there is a possibility that horticultural activities may have occurred at the site in the past.

Other than the reference to potential horticultural activities at the site, the site contamination enquiry did not identify any other potentially contaminating activities at the site.

## 3.1.3 Contaminated Land Database and Closed Landfill Search

A search of the Contaminated Land Database, maintained within AC's Environmental Health Unit of the Licensing and Compliance Services department, was requested and received on 13 May 2019. A search of the AC Closed Landfill Database was also requested and received on 17 April 2019. Copies of these responses are presented in Appendix D.

AC stated the following information of relevance to this investigation:

- There is no contamination information held within AC records for the site; and
- The site is not on AC's list of council owned or managed closed landfills, however, private landfilling is still possible.

No other information of relevance to this investigation was obtained from the Contaminated Land Database and Closed Landfill Search.

## 3.1.4 Hazardous Substances and Incidents Report

The Environmental Protection Agency (EPA) maintained a list of reported hazardous substance incidents over the period July 2006 – December 2011. A review of the EPA register over this period, accessed 2 May 2019, identified no incidents within 500 m of the site.



# 3.2 Historical Aerial Photographs

Historical aerial photographs were sourced from Retrolens<sup>®</sup>, AC Geomaps and Google Earth Pro<sup>®</sup>. These can be found in Appendix E and are described in Table 2 below:

Table 2: Aerial Photograph Review

Year	Reference	Observations
1960	Retrolens (black & white, earliest available image)	The site is rural land in pasture, comprised of multiple paddocks with some trees present along fence lines. Three small buildings are present at the site's western boundary, with two in the site's south-western portion and the other in the site's north-western portion. Three single buildings are also present in the south-eastern corner of the site. A large river is present directly north and west of the site, with a smaller stream in the site's northern portion feeding into it. The main road of the area runs adjacent to the site's southern boundary. Land use surrounding the site is rural. Rural residential dwellings are present directly adjacent to both the south-eastern and south-western corners of the site, as well as the centre of the site's eastern boundary.
1972	Retrolens (black & white)	Land use at the site remains as rural. Additional buildings have been erected in the south-eastern corner of the site, including a long rectangular building presumed to be a farm shed or barn. Land use surrounding the site remains as rural with some rural residential properties. A large oval-shaped track presumed to be a horse racing track is present adjacent to the site's south-eastern boundary.
1988	Retrolens (black & white)	The site and surrounding area remain largely unchanged from 1972 aerial imagery.
2003-2004	AC Geomaps (colour)	Land use at the site remains as rural and the site remains largely unchanged from 1988 aerial imagery. A single residential dwelling is now present east of the farm buildings within the south-eastern corner of the site. Land use surrounding the site continues to be rural and rural residential.
2010-2011	AC Geomaps (colour)	Land use at the site continues to be rural and the site remains largely unchanged from 2003-2004 aerial imagery. The stream in the northern portion of the site looks to flow into dug out channels in the north west and the centre of the site. An un-paved vehicle track is now present in the north-western portion of the site. A small, oval-shaped patch of bare land is present in the north-western corner of the site, otherwise the site remains in pasture. The rectangular shed/barn in the south-eastern corner of the site is no longer present. Land use surrounding the site continues to be rural and rural residential.
2013	Google Earth Pro (colour, most recent image available)	The site and surrounding land remain largely unchanged from 2010-2011 aerial imagery.



# 3.3 Landowner Information

During site visits by 4Sight staff on Wednesday 17 April 2019 and Friday 13 March 2020, informal discussions were undertaken with the landowner as to their knowledge of current and past activities on the site. To the landowner's knowledge, the site has historically been used for agricultural purposes and no potentially contaminating activities are currently or have previously occurred at the site during their time of ownership.

As the site has historically been used for agricultural purposes, there is the potential for superphosphate soil fertilisers to have been applied on the site. However, on the basis that the proposed development is for residential land use (as opposed to the more sensitive rural residential land use), residual cadmium in soils from repeated historic fertiliser applications is highly unlikely to present a risk to human health.

# 4 SITE INVESTIGATION

# 4.1 Site Walkover

Site visits were undertaken on Wednesday 17 April 2019 and Friday 13 March 2020 by 4Sight staff. The site visits involved a walkover discussion with the landowner to identify current features at the site. Photos of the site are presented in Appendix F. The following observations were made during the site visit:

## 4.1.1 The Site

- Land use at the site is rural, with the majority of the site in pasture and comprised of multiple paddocks. Minor
  areas of vegetation are also present, specifically planted trees adjacent to the vehicle accessway along the site's
  western boundary and some smaller patches of riparian vegetation adjacent to the watercourse in the northern
  portion of the site;
- There are several buildings located on the site, primarily farm sheds and structures used to store farming materials, including the following:
  - A single shed, constructed of corrugated iron, directly south west of the area subject to redevelopment;
  - A three walled, open shed directly south of the shed mentioned above, currently being used to store firewood. The shed has a corrugated iron roof and is otherwise constructed of timber with some potential asbestos containing material (ACM) cladding on the eastern and western exteriors of the building. Sections of the potential ACM cladding on the western exterior of the building are broken. The building rests on a concrete slab which also extends to the north and west of the building. Adjacent to the southern side of the building are pieces of disused corrugated iron, timber and fencing wire;
  - A small shed, constructed of corrugated iron and timber, housing a water pump south of the above buildings in the eastern side of the vehicle accessway along the site's western boundary;
  - A single shed, constructed of corrugated iron and timber, in the north-western portion of site adjacent to the site's western boundary. Adjacent to the eastern and western sides of this building are miscellaneous materials, including disused concrete, a single steel farm gate and a rusted drum/pipe;
  - A single shed, constructed of steel, south east of the building mentioned directly above. Adjacent to the
    eastern side of the building are a number of disused pieces of plastic pipe. Adjacent to the south-eastern
    side of the building is a small pile of stone aggregate;
  - Steel cattle yards are present in the south-eastern portion of the site. Adjoined to the southern extent
    of the stock yards are corrugated iron sheds. An additional concrete building with corrugated iron roofing
    is located north of the stock yards and is likely used for agricultural purposes; and
    - A single residential dwelling is present in the south-eastern corner of the site.
- A vehicle accessway runs along the perimeter of the site along the western and northern boundary as well as through the centre of the site in a north-south alignment adjacent to the watercourse;
- A dug out/straightened drainage channel is present in the southern portion of the site. The channel is currently dry and links to the watercourse which flows through the centre of the site;



- Four mounds of bulk lime were present in the western portion of the site. These had been delivered to the site and were due to be spread on site. They had been spread at the time of the second site visit;
- A number of tree branches are piled in the centre of the paddock in the north-western portion of the site, adjacent to the western boundary. No evidence of previous burning activities was observed;
- There was no evidence of significant historic land disturbance activities such as uneven ground or bare earth, or former structures at the site;
- The site is generally tidy, with minimal rubbish or disused equipment visible. There is no visual evidence of contamination such as oil or grease, no areas of significant stressed or dying vegetation and no evidence of current or historical above/underground storage tanks, sumps, pits or lagoons; and
- Land surrounding the site is comprised of rural and rural residential land. Significant surroundings include a wetland area and stream directly north of the site which connects to the watercourse located on the site, a large white barn adjacent to western boundary with stacked hay bales and farming equipment present, and a single rural residential property located in the centre of the southern boundary of the site.

## 4.1.2 The Piece of Land

The area of the site subject to redevelopment is currently in pasture and consists of a natural raised hill which spans across multiple paddocks, as well as a flat area of paddock adjacent to the southern boundary of the site. No buildings or structures and no visible signs of contamination are currently present within these areas.

# 5 CONCLUSIONS

4Sight Consulting Ltd (4Sight) has been engaged by Stratford Properties Ltd (or 'the client') to undertake a Preliminary Site Investigation (PSI) at 278 Clevedon-Kawakawa Road, Clevedon (the site). This investigation included reviewing the site's history and field observations.

The key findings of this PSI are:

- The site occupies an area of approximately 520,000 m<sup>2</sup> of rural land of relatively level topography in Clevedon in the Auckland region and is currently subject to a Private Plan Change to be re-zoned from Rural Coastal to Rural Countryside Living under the Auckland Unitary Plan: Operative in Part (AUP: OP). Given the limited countryside living development opportunities at the site due to the extent of flooding constraints, only a portion of the site is proposed to be redeveloped;
- Proposed redevelopment of the site includes the addition of multiple new residential dwellings on a naturally
  raised area of land (approximately 41,060 m<sup>2</sup>) as well as a relatively level area (approximately 13,550 m<sup>2</sup>) in the
  south-western portion of the site (collectively the 'Piece of Land'). The remaining area of the site will continue to
  be in use as rural production land;
- During site visits by 4Sight staff, no buildings or structures and no visible signs of contamination were identified within the Piece of Land;
- A review of historical aerial images identified the site has been in use as rural land in pasture, comprised of multiple paddocks from at least the 1960's - present. Small, singular farm buildings have been present on the site's western boundary and south-eastern corner during this time. There has been no evidence of significant land disturbance or presence of structures within the Piece of Land during this time;
- The site is currently vacant rural land of relatively level topography with an area of naturally raised land in the site's south-western portion. The site is in pasture with a watercourse flowing in a north-south orientation through the site's centre with dug out, straightened channels in the site's southern half. The Piece of Land currently comprises a natural raised hill area with a grassed ground cover which spans across multiple paddocks, as well as a relatively level paddock in the south-western corner of the site;
- Several small-scale farm sheds are present in the western portion of the site, outside of the Piece of Land, constructed of corrugated iron and timber, with the cladding of one shed constructed of potential ACM in deteriorating condition. It is noted that the proposed development of the site will include the amalgamation of the area in which these sheds are located with the neighbouring property. Stock yards, farm sheds and a residential dwelling are also present in the south-eastern corner of the site;



- Property files and a Site Contamination Enquiry obtained from AC, as well as a search of the AC Contaminated Land and Closed Landfills Databases did not identify any potentially contaminating activities that are currently or have historically occurred on the site; and
- No hazardous substances incidences have occurred on the site or any surrounding properties according to a review of information maintained by the Environmental Protection Agency (EPA).

Based on the findings of this investigation the following recommendations have been made:

- Based on observations during the site visit and review of background material, it is considered there is no record
  of HAIL activities that are currently or have previously been undertaken on the Piece of Land. In addition, the
  remainder of the site will continue to be used as production land. On this basis, the NESCS is not applicable to the
  proposed subdivision, change of land use and soil disturbance associated with the residential development of the
  site;
- Soils within the Piece of Land have not been subject to HAIL activities, and as such it is considered highly unlikely that contaminants in soil would pose a risk to human health. If soils are to be excavated they are suitable for reuse on the site from a human health risk perspective. If soils are to be disposed of off-site, they would likely be considered as cleanfill, however this should be confirmed through analysis and confirmation with the disposal facility prior to removal from the site; and
- There is the potential for asbestos in shallow soils associated with the use of asbestos containing building materials in buildings at the site, outside of the Piece of Land. The NESCS is not applicable to the remainder of the site, outside of the Piece of Land, as long as it continues to be in use as production land. However, should removal of this building be required, an asbestos survey of the building should be undertaken and, should ACM be confirmed, the removal/demolition should be managed in accordance with the Health and Safety at Work (Asbestos) Regulations 2016, and the WorkSafe New Zealand Approved Code of Practice for the Management and Removal of Asbestos.

This investigation and associated reporting have been carried out, supervised and revised by suitably qualified and experienced practitioners (SQEP) in accordance with the NESCS.



# REFERENCES

Auckland Council Geomaps. (2017). Retrieved from https://geomapspublic.aucklandcouncil.govt.nz/viewer/index.html. Accessed April 2019.

- Environmental Protection Agency [EPA]. (2011). *Hazardous Substance Incidents Reports*. Retrieved from <a href="http://www.epa.govt.nz/about-us/monitoring/Pages/HS-incident-reports-archive.aspx">http://www.epa.govt.nz/about-us/monitoring/Pages/HS-incident-reports-archive.aspx</a>, accessed December 2018.
- Geological and Nuclear Sciences [GNS]. (2017). New Zealand Geology Web Map. Retrieved from <u>http://data.gns.cri.nz/geology/</u>, accessed April 2019.

Google Earth. (2018).

- Ministry for the Environment. 2003 (revised 2011). *Contaminated Land Management Guidelines No. 1: Reporting on Contaminated Sites in New Zealand*. Ministry for the Environment, Wellington, New Zealand.
- Ministry for the Environment. 2011. Resource Management (National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health) Regulations 2011. Ministry for the Environment, Wellington, New Zealand.

# LIMITATIONS

This document does not include any assessment or consideration of potential health and safety issues under the Health and Safety at Work Act 2015. 4Sight Consulting has relied upon information provided by the Client and other third parties to prepare this document, some of which has not been fully verified by 4Sight Consulting. This document may be transmitted, reproduced or disseminated only in its entirety.

From a technical perspective, the subsurface environment at any site may present substantial uncertainty. It is a heterogeneous, complex environment, in which small subsurface features or changes in geologic conditions can have substantial impacts on water, vapour and chemical movement. 4Sight Consulting's professional opinions are based on its professional judgement, experience, and training. These opinions are also based upon data derived from the testing and analysis described in this document. It is possible that additional testing and analysis might produce different results and/or different opinions. This document was prepared based on information provided by others. Should additional information become available, this report should be updated accordingly.



Appendix A:

**Preliminary Development Plans** 



COPYRIGHT© THIS DRAWING AND PARTS THEREOF ARE COPYRIGHT TO LANDS AND SURVEY (AUCKLAND) LIMITED, AND SHALL NOT BE USED, REUSED, COPIED, REPRODUCED OR OTHERWISE UTILISED WITHOUT THE WRITTEN PERMISSION OF LANDS AND SURVEY (AUCKLAND) LIMITED OR ITS ASSOCIATED COMPANIES. LEGEND: RURAL - RURAL COASTAL RURAL - COUNTRYSIDE LIVING CAD AND PRODUCTION BY: 🛇 lands & Survey Auckland | Whangarei | Christchurch | Wanaka Ph 0800 SURVEY www.landsandsurvey.co.nz DRAWING TITLE: **PROPOSED REZONING** CLIENT NAME: STRATFORD PROPERTIES LIMITED CLIENT DETAILS: 272&278 CLEVEDON-KAWAKAWA ROAD CLEVEDON CONCEPT REV. DESCRIPTION A ORIGINAL ISSUE B AMENDMENTS BY DATE DS 17/07/19 DS 02/10/19 SURVEYED DESIGNED DRAWN PG 19/12/18 DS 02/10/19 TG 02/10/19 APPROVED SCALE (A3) 1:5000 100 150 scale bar 200 250m 50 0 DRAWING REFERENCE <sup>rev</sup> **B** 117536-160

Drawing Plotted: 10/2/2019 3:27 PM





ASEMENTS		
NT	DOMINANT	
NT	TENEMENT	
IED	BENEFITED	
1	LAND	
2	LOTS 13 & 14	
N	HEREON	
3	LOTS 1-11, 12 & 14	
Ν	HEREON	
4	LOTS 1-11 & 12	
N	HEREON	
4	LOTS 1-11 & 12	
N	HEREON	







Appendix B:

**Property File** 

Informer Higher and 3015:278 怂 NUMES DATE annu loft EP.A.La Alta Albahima Playon Deringe spring a44 17/110 MANUKAU City Council Building Permit Application Anna Ca Application for 121 creeks 
 Directly
 particular plant of property. In constraint provide shares. To plant 04 1 3015/2.78 Application for BUILDING PERMIT Automorphic to advant CONSTANT POPER ( CHAMBERLIN) F 6 KW WIL DATE MERCING S [11] (21 COTAL 0 OF 14/28/28, MORE 876 CLEVIED KRANNE MERLESUN Non-siles, saling neights, by 244 01/2 Fooriga Mattery and Survivation with Generate Ease Trains with Hors, Society and I Mail construction Nati construction Nati leasing Foorings 041 10/00 041 10/00 041 1/0 044 / 044 / 044 / 044 / The Construction Post Construction Real Ensuing Insulation Second hand Australia Section 1924 person y-Sublim alter Sin 1-The plane that with St. Garance that there is the harding and bet i (201997). Mo down gy plan - where that all Mo down gy plan - where the form Active grand to a set of the set Frankle (norodna salitica interest Properties Free 116-1256 5 Dool Experies has Refer, have seeded from hilly on the pin-meterial pits and Pitching in an input the pin-Pitching and the second -Valvicia Crossing Inspection 15 3.000 -01 BOND Hand lift - Fitneric Sciencest. Report for Relation Sciences and Sciences Parts - Fitneric Sciences Sciences Parts - Fitneric Sciences Sci Apresment Bederteting: Inc.is Jat. No. Converte 200 F 5 2 See 8.2. NTINUE DATE GLUE. Ineress Iner PL S.H.Geg 2.4.8.09 Z.Em. 13 Rin Barton AL alater 13 Rin Barton AL alater Total Fees Payable is 3.8.82 - 10 -feeds Noise Class Bir WARD OFFICE NOTFIND OF ADDITIONAL INCOMMATION DIDULTS? AND/YOR REASON DOG THE AV ETMI MILLONG FEMALES MURLAGE CALLUR JUSTAMIN DIS DESIZ Tri Desiza fikukini di dani silami abelige 963 Peter Changer 13,852-50 Fass Received now A decision of the second s OHECKLINE NONSPECT J29788. The state CANADA STREET CONTRACTOR OF THE STREET ACTER TO INSIDE OF FOLDER FOR HALDING PERMIT PRODUCTION CHIECK LIK NATURE OF SULCINE NORS 3.9. NEW SHITE, ADDITIONAL FACTORY, MIC SH Relocate Stilling + Adas + carpent Contractory of the Audit as the در <sup>د</sup> مشعر مشعر د Construction of the and 23 Clevedon Id Property Ealer 3 0 1 5 2 7 8 Attention M. Sullivan Strend 20 - Lite Destin BB - transing table 2 - prover Parties - Artifenti on M. Stallarman Monucliana Cal-CEA TECHNCA GAVIES Inghast Project Hanger, Std. Hypetika Series Stadio Series ۲ ۲ APRUCATION FOR PERMIT FOR AINAGE WORK. SANITARY PLUMOING OF DRAINAGE WORK SANITARY PLUMBING OR LATERSTORE 214 C. LA. Planter 52.94 other from 25/1//9/ Planter 52.94 other from 25/1/9/ Planter of the form 1000 form MARILEAU Gity Carees As pass pace 9106.... Mension City-Council Monaton Rag Mension City ER (116) Fax 217-6323 9/44/450 alia 1 10 pat Ald 646071 - fo Manufas City Council Provate Bag Manufas City OX 7161 A Tra-Time Inspector DEANTID · · · B March Side Ce l Nr Poter Churchardin Mend Haland Nava Kawa Bay Nand ND 5 \_\_\_\_\_ MITT & hat aff the way - & Browners star Biter Chan hadlin + Kanhan St. PDS, Before 
 Ai belt

 Ben

 Ben
 </tr Bater Clean pertin + Kanhan & ROS, Rodal 24/4/94 CONC. FLINE SLAD (the undersigned), hences accels for a participantie work deac that have, and set out in plane attached have is, in the same of the independence of previous of previous of the previous of t Pasekura Dear Peter the enderstyped, hereby apply for a participative work deep herein, to be carried out in the undermaniposed possibles December 1 - 5/mer ding - 0426 (681) prest 16 - 5245 - 046 dra d'anne 28/1/21 - 046 While Not All MA GUNS rander to be entries of a the order where a product of the order where have any shower and the order of the o 510-51000 101 00 - Port Allow an Source re: 288 Kawa Kawa Ray Road-MACHE . . . . 14/12 / mast Ald Holdon; - St ) This is to confirm that I inspected the foundation construction for the develop at the above address during March 1991 with the object of providing evidence of the structural sounderess for a lature building permit application. Service View of Property View of No. of Batter \_\_\_\_\_\_ 21 No. of Batter 31 No. of Views \_\_\_\_\_\_ 21 No. of Batter \_\_\_\_\_\_ 21 No. of Batter 32 No. of Views \_\_\_\_\_\_ 21 No. of Batter Batter Constituted 32 No. of Views \_\_\_\_\_\_ 21 No. of Batter Batter Constituted 32 No. of Views \_\_\_\_\_\_ 22 No. of No. of Batter Batter 32 No. of Views \_\_\_\_\_\_ 22 No. of No. of Service Batter 21 No. of Views \_\_\_\_\_\_ 22 No. of No. of Service Batter 21 No. of Views \_\_\_\_\_\_ 22 No. of No. of Service Batter 21 No. of Views \_\_\_\_\_\_ 22 No. of No. of Service Batter 21 No. of Views \_\_\_\_\_\_ 22 No. of No. of No. of Service Batter 21 No. of Views \_\_\_\_\_\_ 22 No. of No. of No. of Service Batter 21 No. of Views \_\_\_\_\_\_ 22 No. of No. Ster syster Cesseller N00901 - - -Description of Descent West 4-12-91 K-26 Verminister in Populate Rock
 10 Min. of Bastrs \_\_\_\_\_\_ (2 Nit. of Bastrs
 10 Nit. Of Version Version
 11 Nit. Of Version Version
 11 Nit. Of Version
 11 Nit. Of Units
 11 Nit. ALL PRACES 417/01 Ald .. A Unfortunately the notes I took at the time have been lost in our den house ships, 11/17/ 11 4/4 \$1 eich house bhile. The building was a setablish wood method for known and a setablish wood intheir (10 x 10 gates) reader and a setablish was gates). It is open working known and a setablish the known and a setablish and the for any setablish of setablish the setablish and any setablish paratical. Although the controls setablish the the for any setablish predicts. Although the controls easies that the work would pred-te setablish the the setablish. BACING . . . . If in pompatian with sciping such, use full details of membra and a 6-1591 K.Hame If in contraction with setting work, give hull catalla of regains and site as FAMILA ... 4/17/41 MILS Dauge was so bears - Ryste, trend a sical ag posts set in congrade lock was being carried Mr Brian Kells had a any inversioner Septie tout + sonkage do BALLAS ..... 4/12/91 34 Land out with Sulling heaty places Altrians Descring Daty 4:12-91 ft 10) Test mension uno el presento uno <u>MA</u> 10) Teste mensione el presento y uno <u>MA</u> 10) Teste mensione su el presento y uno <u>MA</u> 10) Teste mensione su el presento y <u>ano el presento y</u> <u>12300</u> 11) Teste mensione de al presento presento y <u>12300</u> 12) Teste presento de al presento presento y <u>12300</u> 13) Teste presento de al presento presento y <u>12300</u> 13) Teste presento de al presento presento presento y <u>12300</u> 13) Teste presento de al presento presen -MA 11111000, DEATERS 4/ 17/91 4944 85 INTERNAL SPEATHING VALUE AND THOUT & BOOKS . 10/12/9/ 454.8 Distances to pre-most DATED INE 23 - 10 - 92 card Orthomes No. (Flumber) DATED mine 2.3 - 1.0 - 9.1 , one of Standard I am confidere that this building ageners dreamer Title the boot name Tetis the bet : Yolars faithers 
 Statement and a Statement
 Proceedings and a Statement

 Statement (1 - 0 - 0)
 Statement (1 - 0 - 0)

 Statement (2 - 0 - 0)
 State Stat Materiansen Planking Certificate of Campistano dinta\_\_\_\_NeglingOnitespe Texts\_270\_000 ----- BILLA Restance of the second manie Boland Graemo Chamberlin, scot Fice. Project Manager Highway 16. territor ter 

ふりいろ

20. 2 D.

ò

Ę

a

MICROFILMED ON 3015 278 0.2 3/4 199

.

ารับแบบข้ามกล่างร่าง

ż

ò.

å

₩.

8

å а

V

2

э

- 6-

11

a

÷

ò

э



de.





Appendix C:

Site Contamination Enquiry



29th April 2019

4Sight Consulting Limited 201 Victoria Street West Auckland

Attention: Shannen Barns

Dear Shannen

## Site Contamination Enquiry – 278 Clevedon Kawakawa Road, Clevedon

This letter is in response to your enquiry requesting available site contamination information for the above site. The following details are based on information available from the former Auckland Regional Council records system and information currently held by the Auckland Council Natural Resources and Specialist Input Unit. The details provided below exclude any property information held by the former district/city councils.

No pollution incident files regarding spills/contamination were found for the above site. The general catchment file and site visit file for the catchment 801-830 were not searched. These files contain pollution incidents where the source of pollution was not traced to a particular site, site visits where no follow-up correspondence was required and some information from archived files.

If the above site is coastal or beside a river, it is possible that historic, unconsented reclamation may have occurred. The Auckland Council Specialists Unit Coastal Team may be able to provide further information.

The records reviewed as part of this Site Contamination Enquiry search do not identify individual horticultural sites in the region. However, there is a possibility that horticultural activities may have occurred at the site. The local Auckland Council customer service centre, specific to the area of the site may be able to provide relevant information where former horticultural sites have been mapped.

If you are concerned that a historic land use (such as filling) may have caused the underlying soils to become contaminated, it is recommended that you obtain an independent environmental assessment of the site. Staff from the Auckland Council Earthworks and Contaminated Land Team can provide advice on the results of any evaluation in terms of site remediation and/or potential consent requirements.

The former Auckland Regional Council and current databases were searched for records of **closed landfills**, **bores**, **air discharge**, **industrial and trade process consents**, **contaminated site discharge consents**, **and environmental assessments** within approximately 200 metres of the site. No consents were identified.

The details provided are in accordance with the obligation to make information publicly available upon request. While the Auckland Council has carried out the search using its best practical endeavours, it does not warrant its completeness or accuracy and disclaims any responsibility or liability in respect of the information. If you or any other person wishes to act or to rely on this information, or make any financial commitment based upon it, it is recommended that you seek appropriate technical and/or professional advice.

In addition, further site specific pollution incidents may be held at the area office below. It is recommended that you contact the local customer service centre of the Auckland Council, specific to the site being investigated: Ground Floor, Kotuku House, 4 Osterley Way, Manukau Central, as they also may hold files with further relevant information.

I trust that this answers your query. If you wish to discuss the matter further, please contact **Andrew Kalbarczyk** on 301 0101. Should you wish to request any of the files listed above for viewing, please contact the Auckland Council Call Centre on 301 0101 and note you are requesting former Auckland Regional Council records (the records department requires three working days' notice to ensure files will be available).

Please note: the Auckland Council cost recovers officer's time for all site enquiries. A basic enquiry takes approximately 1 - 2.5 hours to search the files and databases in which information is held. As such an invoice for the time involved in this enquiry will follow shortly.

Yours sincerely

Pp. EM Jared Osman Team Leader – Contaminated Air, Noise Specialist Unit | Resource Consents





Appendix D:

**Contaminated Land Database and Closed Landfil Search** 

## Samantha Waters

From:	Claire Lacina <claire.lacina@aucklandcouncil.govt.nz></claire.lacina@aucklandcouncil.govt.nz>
Sent:	Monday, 13 May 2019 1:30 PM
То:	Shannen Barns
Subject:	RE: Contaminated Database Search 278 Clevedon-Kawakawa Road

## Hi Shannen,

This email is in response to your recent enquiry requesting available site contamination information held within the Environmental Health Unit of the Licensing and Compliance Services Department (LCS).

There is no contamination information held within our records for the site 278 Clevedon Kawakawa Road, Clevedon.

Please note that only council's soil contamination records within the LCS department and GIS map have been checked. There may be other soil contamination information held within:

1. A Contaminated Sites Enquiry report, which contains the following information only:

- (A search area of radius 200m is applied by default)
  - Pollution Incidents (incl. air discharges, oil or diesel spills)
  - · Bores
  - · Contaminated site, air discharge and industrial trade process consents
  - · Closed Landfills (council- owned closed landfill sites only)
  - · Air quality permitted activities

How to apply for a Contaminated Sites Enquiry Response: DO NOT apply for this as part of a Property File request. Please follow this link --> <u>https://www.aucklandcouncil.govt.nz/building-and-consents/types-resource-consents/earthworks/Pages/order-site-contamination-enquiry-report.aspx</u>

Please take note of the following when applying:

- Apply under the Company Name if request is on behalf of the company.
- Legal Description(s) of the physical site(s) is/are stated clearly. This is to ensure accurate representation of data.
- Enter preferred Postal Address or PO Box instead of physical address of company.
- Contact Person: Please enter your full name, including e-mail address.

2. Property File for viewing reports or all relevant information relating to the property -Requested from the local service centre, by phone, 09 3010101.

## <u>Please note</u>:

If you are demolishing any building that may have asbestos containing materials (ACM) in it:

- 1. You have obligations under the relevant regulations for the management and removal of asbestos, including the need to engage a Competent Asbestos Surveyor to confirm the presence or absence of any ACM.
- 2. Work may have to be carried out under the control of the person holding a WorkSafe NZ Certificate of Competence (CoC) for restricted works.
- 3. If any ACM is found, removal or demolition will have to meet the requirements of the Health and Safety at Work (Asbestos) Regulations 2016.
- 4. Information on asbestos containing materials and your obligations can be found at <u>www.worksafe.govt.nz</u>.

If ACM is found on site following the demolition or removal of the existing buildings, you may be required to remediate the site and carry out validation sampling. Dependent on the amount of soil disturbance a further consent application may be required.

Paints used on external parts of properties up until the mid-1970's routinely contained lead, a poison and a persistent environmental pollutant. Older paints dating from before 1945 often contained extremely high levels of lead. Dust and flakes from painted surfaces in poor condition are a major cause of lead poisoning in both adults and children. You are advised to ensure that soils affected by old, peeling or flaking paint are assessed in relation to the proposed use of the property. Very sensitive uses such as residential with young children, childcare centres, play areas or recreational land should be considered as high risk. In services or working environments other regulatory requirements may require risk assessment and mitigation.

Ngā mihi, Claire

Claire Lacina | Technical Officer – Contamination, Air & Noise Specialist Input | Resource Consents Ph 09 3522621 (Int 465621) | Mob 021 718 038 Auckland Council, Level 2, 35 Graham Street, Auckland Visit our website: www.aucklandcouncil.govt.nz

From: Shannen Barns <shannenb@4sight.co.nz>
Sent: Monday, 13 May 2019 12:36 PM
To: RECContamination <reccontamination@aklc.govt.nz>; Claire Lacina <claire.lacina@aucklandcouncil.govt.nz>
Subject: Contaminated Database Search 278 Clevedon-Kawakawa Road

Hi Claire

Apologies for the late notice but I was wondering how quickly you could do a search of the contaminated land database for the following property:

278 Clevedon-Kawakawa Road (legal description LOT 1 DP 146882)

We are undertaking a PSI under a short timeframe and ideally need this search completed today. I'm assuming there's no record of HAIL activities on the property as it has always been rural farm land and the Site Contamination Enquiry did not return anything, so I'm assuming your search wouldn't take too long (3)

Thank you and sorry again for the short notice!

Shannen Barns Environmental Consultant

Mobile: 027 748 3438



201 Victoria Street West, Auckland Central 1010 PO Box 911 310, Victoria St West, Auckland 1142 <u>4Sight.Consulting</u><u>LinkedIn</u>

NOTICE - This e-mail is only intended to be read by the named recipient. It may contain information which is confidential, proprietary or the subject of legal privilege. If you are not the intended recipient please notify the

sender immediately and delete this e-mail. If you are not the intended recipient you should not copy this e-mail or use the information contained in it for any purpose nor disclose its contents to any other person. Legal privilege is not waived because you have read this e-mail. 4Sight Consulting accepts no responsibility for electronic viruses or damage caused as a result of this email or for changes made to this email or to any attachments after transmission from 4Sight Consulting. You should not distribute or publish the contents of this email or any attachment without the prior consent of 4Sight Consulting



CAUTION: This email message and any attachments contain information that may be confidential and may be LEGALLY PRIVILEGED. If you are not the intended recipient, any use, disclosure or copying of this message or attachments is strictly prohibited. If you have received this email message in error please notify us immediately and erase all copies of the message and attachments. We do not accept responsibility for any viruses or similar carried with our email, or any effects our email may have on the recipient computer system or network. Any views expressed in this email may be those of the individual sender and may not necessarily reflect the views of Council.

## Samantha Waters

From:	Lorraine Hamilton <lorraine.hamilton@aucklandcouncil.govt.nz> on behalf of closedlandfills <closedlandfills@aklc.govt.nz></closedlandfills@aklc.govt.nz></lorraine.hamilton@aucklandcouncil.govt.nz>
Sent:	Wednesday, 17 April 2019 3:37 PM
То:	Shannen Barns
Subject:	RE: Closed Landfill Search - 278 Clevedon Kawakawa Road

Hi Shannen,

The site is not on our list of council owned or managed closed landfills, however, private landfilling is still possible.

I recommend checking the property file, the LIM report and complete a contamination enquiry through here:

## How to apply for a Contaminated Sites Enquiry Response:

To apply online follow this link --> <u>https://www.aucklandcouncil.govt.nz/building-and-consents/types-</u>resource-consents/earthworks/Pages/order-site-contamination-enquiry-report.aspx

Please take note of the following:-

Apply under the Company Name if request is on behalf of the company.

Legal Description(s) of the physical site(s) is/are stated clearly. This is to ensure accurate representation of data.

When applying online, please enter preferred Postal Address or PO Box instead of physical address of company.

HAIL, Soil Contamination and impact on Human Health:

The Ministry for the Environment has put together a Hazardous Activities and Industries List to help identify sites where the soil may be contaminated.

If you want to enquire about soil contamination or to enquire on whether we may have record of HAIL activity at a site, email reccontamination@aucklandcouncil.govt.nz

## More information can be found on our website

Kind regards,

Lorraine Hamilton | Closed Landfill Management Specialist Engineering & Technical Services Unit Infrastructure & Environmental Services Department

## Mobile 021 838 943

Auckland Council, Level 2 North, Bledisloe House, 24 Wellesley St, Auckland Central, Auckland 1010 Visit our website: <u>www.aucklandcouncil.govt.nz</u>

**From:** Shannen Barns [mailto:shannenb@4sight.co.nz] **Sent:** Monday, 15 April 2019 3:40 p.m.

## To: closedlandfills Subject: Closed Landfill Search - 278 Clevedon Kawakawa Road

Hi there

I am undertaking a Preliminary Site Investigation at the following site:

- Address: 278 Clevedon Kawakawa Road, Clevedon, 2585
- Legal Description: LOT 1 DP 146882
- CT Number: NA87C/391
- Area: 52 ha

Do you hold any information on contamination issues or closed landfill evidence at the site, or any historical reports?

Many thanks,

Shannen Barns

Environmental Consultant

Mobile: 027 748 3438



201 Victoria Street West, Auckland Central 1010 PO Box 911 310, Victoria St West, Auckland 1142 <u>4Sight.Consulting</u><u>LinkedIn</u>

NOTICE - This e-mail is only intended to be read by the named recipient. It may contain information which is confidential, proprietary or the subject of legal privilege. If you are not the intended recipient please notify the sender immediately and delete this e-mail. If you are not the intended recipient you should not copy this e-mail or use the information contained in it for any purpose nor disclose its contents to any other person. Legal privilege is not waived because you have read this e-mail. 4Sight Consulting accepts no responsibility for electronic viruses or damage caused as a result of this email or for changes made to this email or to any attachments after transmission from 4Sight Consulting. You should not distribute or publish the contents of this email or any attachment without the prior consent of 4Sight Consulting



CAUTION: This email message and any attachments contain information that may be confidential and may be LEGALLY PRIVILEGED. If you are not the intended recipient, any use, disclosure or copying of this message or attachments is strictly prohibited. If you have received this email message in error please notify us immediately and erase all copies of the message and attachments. We do not accept responsibility for any viruses or similar carried with our email, or any effects our email may have on the recipient computer system or network. Any views expressed in this email may be those of the individual sender and may not necessarily reflect the views of Council.



Appendix E:

**Historical Aerial Photographs**




320m

AA4755 - 278 Clevedon-Kawakawa Rd PSI Aerial Photograph of the Site Taken in 1960

Figure prepared for Stratford Properties Ltd by 4Sight Consulting.







AA4755 - 278 Clevedon-Kawakawa Rd PSI Aerial Photograph of the Site Taken in 1972 Figure prepared for Stratford Properties Ltd by 4Sight Consulting.





N Scale 1:8,000 @ A4

320m

AA4755 - 278 Clevedon-Kawakawa Rd PSI Aerial Photograph of the Site Taken in 1988

Figure prepared for Stratford Properties Ltd by 4Sight Consulting.





Aerial imagery sourced from Auckland Council GeoMap

Copyright: This document and the copyright in this document remains the property of 4Sight Consulting. The contents of this document may not be reproduced either in whole or in part by any means without prior consent of 4Sight Consulting

N Scale 1:8,000 @ A4

320m

AA4755 - 278 Clevedon-Kawakawa Rd PSI Aerial Photograph of the Site Taken in 2003-2004

Figure prepared for Stratford Properties Ltd by 4Sight Consulting.







320m

AA4755 - 278 Clevedon-Kawakawa Rd PSI Aerial Photograph of the Site Taken in 2010-2011

Figure prepared for Stratford Properties Ltd by 4Sight Consulting.





N Scale 1:8,000 @ A4

320m

AA4755 - 278 Clevedon-Kawakawa Rd PSI Satellite Photograph of the Site Taken in 2013 Figure prepared for Stratford Properties Ltd by 4Sight Consulting.





Appendix F:

Photolog







Photo 2: Western portion of the Piece of Land. Photo taken facing west.





Photo 3: Northern portion of the Piece of Land. Photo taken facing south.

Photo 4: Southwestern portion of the Piece of Land. Photo taken facing north east.



Photo 5: Southern extent of the site, comprising the southern portion of the Piece of Land/area proposed as the shared accessway. Photo taken facing south.



Photo 6: Southern extent of the site, comprising the southern portion of the Piece of Land/area proposed as the shared accessway. Photo taken facing south east towards dwelling of 294 Clevedon-Kawakawa Road.



Photo 7: Facing north west towards large white barn directly west of the site.



Photo 9: Shed constructed of corrugated iron and timber building materials in north-western portion of the site. Photo taken facing north.



Photo 8: Pile of branches in north-western portion of the site. Photo taken facing north west.



Photo 10: Eastern side of shed pictured in Photo 9. Disused concrete, steel farm gate and rusted drum/pipe present. Photo taken facing north.



Photo 11: Corrugated iron at the eastern exterior of the shed pictured in Photo 9.



Photo 12: Northern exterior of the shed pictured in Photo 9.





Photo 13: Stacked hay bales, small corrugated iron shed and white barn directly west of the site. Fence line represents western boundary of the site. Photo taken facing south west. Photo 14: Shed in south western portion of site adjacent to current accessway. Cladding of building is constructed of potential ACM. Photo taken facing south east.





Photo 15: Contents of shed pictured in Photo 14 upon secondary site visit - pieces of timber, garage doors.

Photo 16: Area of proposed shared accessway. Photo taken facing south.



Photo 17: Western extent of the Piece of Land, including area proposed for the shared accessway. Photo taken facing south.

Photo 18: View from the centre of the raised area (Piece of Land), facing north west towards white barn.



Photo 19: Close up of exterior of building in southwestern portion of the site, showing potential ACM.



Photo 20: Disused corrugated iron, timber and wire adjacent to southern side of building constructed of potential ACM, as pictured in Photo 12.







Photo 22: Additional building in south-western portion of the site, directly north east of the building which contains potential ACM. Photo taken facing north east.



Photo 23: South-western boundary of the site represented by tree line in the left of photo. Photo taken facing north towards green pump shed pictured in Photo 15.



Photo 24: Dug out channel in southern portion of the site. Photo taken facing east.



Photo 25: Current residential dwelling in south-eastern portion of the site. Photo taken facing north.



Photo 26: Stock yards present in south-eastern portion of the site. Photo taken facing west.





Photo 27: Building associated with stock yards in southeastern portion of the site. Photo taken facing south west.

Photo 28: Closer view of building associated with stock yards in south-eastern portion of the site.



Photo 29: South-western area of the site, comprising the Piece of Land. Photo taken facing east with dwelling of 294 Clevedon-Kawakawa Road in distance.



Photo 30: Watercourse in the central north-western portion of the site. Photo taken facing north west.





Photo 31: Concrete building with corrugated iron roofing located within the paddock directly north of the stock yards in the south-eastern corner of the site. Photo taken facing north west.

Photo 32: Watercourse adjacent to vehicle access in the centre of the site. Photo taken facing west.





Photo 33: Green steel shed/disused pipes in the western portion of the site, south east of the large white barn. Photo taken facing west.

Photo 34: Southern side of building pictured in Photo 27, adjacent to a small pile of stone aggregate. Photo taken facing north west.



Photo 35: Covered mounds in western portion of the site, contents of which are bulk lime (as confirmed by the landowner). Photo taken facing east.



Photo 36: Distant view towards area of former mounds, taken during secondary site visit. No mounds were observed and no impact to surface soils was observed.

www.4sight.consulting