

 <b>Eastern Busway</b>	Prepared by:	G.W	<b>Eastern Busway</b> <b>Groundwater Level Monitoring</b> <b>EB21_DH301_P Piezometer Results</b>
	Checked by:	MC	
	Date:	10/08/2023	
	Figure No.:	1	




Prepared by:	G.W
Checked by:	MC
Date:	10/08/2023
Figure No.:	1


**Eastern Busway**  
**Groundwater Level Monitoring**  
**EB21\_DH303\_P Piezometer Results**




Prepared by:	G.W
Checked by:	MC
Date:	10/08/2023
Figure No.:	1

**Eastern Busway**  
**Groundwater Level Monitoring**  
**EB21\_DH305\_P Piezometer Results**




 Eastern Busway	Prepared by:	G.W	<b>Eastern Busway</b>
	Checked by:	MC	<b>Groundwater Level Monitoring</b>
	Date:	10/08/2023	<b>EB21_DH308_P Piezometer Results</b>
	Figure No.:	1	






Prepared by:	G.W
Checked by:	MC
Date:	10/08/2023
Figure No.:	1

**Eastern Busway**  
**Groundwater Level Monitoring**  
**EB21\_DH308A\_P Piezometer Results**




Prepared by:	G.W
Checked by:	MC
Date:	10/08/2023
Figure No.:	1

<b>Eastern Busway</b>	
<b>Groundwater Level Monitoring</b>	
<b>EB21_DH308B_P Piezometer Results</b>	




Prepared by:	G.W
Checked by:	MC
Date:	10/08/2023
Figure No.:	1


<b>Eastern Busway</b>
<b>Groundwater Level Monitoring</b>
<b>EB21_DH309_P Piezometer Results</b>




Prepared by:	C.L.
Checked by:	MC
Date:	10/08/2023
Figure No.:	1

<b>Eastern Busway</b>
<b>Groundwater Level Monitoring</b>
<b>EB21_DH311_P Piezometer Results</b>




 <b>Eastern Busway</b>	Prepared by:	G.W	<b>Eastern Busway</b>
	Checked by:	MC	<b>Groundwater Level Monitoring</b>
	Date:	10/08/2023	<b>EB21_DH315_P Piezometer Results</b>
	Figure No.:	1	




Prepared by:	GW
Checked by:	MC
Date:	10/08/2023
Figure No.:	1

**Eastern Busway**  
**Groundwater Level Monitoring**  
**EB21\_DH318\_P Piezometer Results**



Prepared by:	C.L
Checked by:	MC
Date:	6/09/2023
Figure No.:	1


<b>Eastern Busway</b>	
<b>Groundwater Level Monitoring</b>	
<b>EB21_DH319 Piezometer Results</b>	



Prepared by:	C.L
Checked by:	MC
Date:	5/09/2023
Figure No.:	1


<b>Eastern Busway</b>	
<b>Groundwater Level Monitoring</b>	
<b>EB21_DH322 Piezometer Results</b>	







Prepared by:	W. Nao
Checked by:	MC
Date:	6/10/2023
Figure No.:	1

<b>Eastern Busway</b>
<b>Groundwater Level Monitoring</b>
<b>EB21_DH323_VW1 Piezometer Results</b>




 Eastern Busway	Prepared by:	W.Nao	<b>Eastern Busway</b>
	Checked by:	MC	<b>Groundwater Level Monitoring</b>
	Date:	2/10/2023	<b>EB21_DH323_VW2 Piezometer Results</b>
	Figure No.:	1	




Prepared by:	GW
Checked by:	MC
Date:	5/09/2023
Figure No.:	1

<b>Eastern Busway</b>
<b>Groundwater Level Monitoring</b>
<b>EB21_DH326_P Piezometer Results</b>



Prepared by:	G.W
Checked by:	MC
Date:	4/09/2023
Figure No.:	1

<b>Eastern Busway</b>
<b>Groundwater Level Monitoring</b>
<b>EB21_DH328_P Piezometer Results</b>



Prepared by:	C.L.
Checked by:	MC
Date:	4/09/2023
Figure No.:	1

<b>Eastern Busway</b>
<b>Groundwater Level Monitoring</b>
<b>EB21_DH328A_P Piezometer Results</b>