



KEY

- Roads / Carparks
- Footpaths
- Proposed Compacted Scoria/Gravel Paths
- Existing Vegetation
- Existing or proposed Low Planting

- Proposed Specimen Trees (Deciduous)
- Proposed Specimen Trees (Evergreen)
- Proposed Tall Shrub or Screen Planting
- Bollards
- Main Views
- New Park Signs

LEGEND

22. Established carparks on the edge of the reserve along Melville Place
23. Rationalize existing planting and crown lift trees to create a more open woodland setting. (Initiate further clearance of shrub and tree weed species)
24. Rationalize vegetation on rock outcrop to create view shafts for an outlook/informal play area. Establish permanent paths to the top with low native planting between rocks
25. Establish a footpath connection with steps from carpark to the main footpath
26. Establish new pathways with pedestrian lighting from the Roosevelt Road entrance to the rugby club, upper carpark and Melville Place woodland area (Partially completed)
27. Relocate entrance path away from hedge to improve sight lines
28. Trim back the existing steps to create a 5m clear zone from the rugby field
29. Establish connection to main footpath
30. Establish permanent rows of spectator seating on the bank. Widen & improve the path in front of the rugby club and create a spectator area with a low retained edge, leaner railings and drinking fountain
31. Remove selected existing vegetation along the boundary to allow for a new path and 5m clear zone. Upgrade and relocate rugby field floodlighting to the eastern side of the path. Replace existing fences in disrepair and plant flax along the fenceline. (Completed)
32. Extend the existing footpath to link up with the community centre (Completed)
33. Upgrade the playing surfaces of the rugby fields and increase width to 67.5 with a 5m clear zone around the outside
34. Establish low shrub planting next to the entrance
35. Formalise the pedestrian connection to the carpark with a concrete footpath and replace the existing flax with low ground cover to improve sight lines (Path Completed)
36. Infill shrub planting around the carpark
37. Upgrade the main entrance into the Domain to provide a stronger pedestrian emphasis with basalt walls, lockable gate, decorative paving, mural and shrub and tree planting either side of the driveway
38. Extend the playground to increase the appeal for a wider age group of users, and provide seating for caregivers
39. Install a drinking fountain
40. Install a new toilet facility near playground
41. Establish enlarged paved forecourt to community centre with low basalt walls and decorative paving
42. Construct a semi enclosed courtyard at northern end of community centre with permeable screen
43. Infill planting to establish a continuous screen along boundary
44. Improve drainage outside the athletics/harriers club.
45. Remove section of redundant footpath
46. Widen footpath and create improved connection to Olea Road

LEGEND

1. Upgrade and enhance Olea Road pedestrian entrance and footpath to playground/Community Centre (Completed)
2. Partial removal of row of existing acmena to allow for new path connection. (Completed)
3. Resurface lower netball courts and repair fencing and drainage issues. (Completed)
4. Repairs and resurfacing to the road in front of hall and footpath above the retaining wall
5. Repairs to existing stone wall
6. Install bollards from the hall to the rugby club to prevent informal vehicle access to the playing fields (Completed)
7. Upgrade existing timber steps with concrete and basalt
8. Rationalize existing planting, crown lift trees, to create a more open woodland setting. (Initiate further clearance of shrub and tree weed species)
9. Establish a new concrete path linking Namata Road to the rugby club (with pedestrian lighting) (Path Completed)
10. Upgrade Practice Area (Field 3) with sand based surfacing, drainage & new lights
11. Further specimen tree planting and screening of existing fenceline.
12. Construct a lookout with basalt walls and seating to take in views to east over the city
13. Install picnic tables
14. Establish low screen planting along northern part of the top of the existing stone wall
15. Continue established row of corokia around the apex of the fenceline
16. Upgrade entrance with new bollards and signage (Completed)
17. Upgrade/resurface carpark and construct a footpath along northern edge of the rugby clubrooms linking with the existing steps
18. Plant further bottlebrush along bank to complete the row and establish low planting along the steep bank
19. Interplant existing trees with pohutukawa to eventually complete the established discontinuous row
20. Replace existing bollards around carpark with parks standard
21. Remove existing timber fence and create a suitable formed pedestrian entrance to the park from Melville Place

OLEA ROAD

ORANGA KINDERGARTEN

HULL PLACE

33 FIELD 2

33 FIELD 1

HALL

TEPAPA RUGBY / SQUASH CLUB

CARPARK

FIELD 3 (PRACTICE AREA)

NAMATA ROAD

ROOSEVELT RD

MELVILLE PLACE

