



Photo of Existing SW outlet at location of proposed new outlet -location as surveyed at rear of 13 Jaylo Place (see SMP drawings)









Photo taken looking north towards rear of 25 Jaylo Place – note elevated house position and pest plant (Woolly Nightshade)



Photos of drainage reserve at rear (north side) of 1 and 3 Verissimo Drive





Photo taken looking east along edge of Naylor's Reserve







Photo taking looking north towards 79 Naylor's Drive








Photo taken looking north-west up the drainage channel area.








Photo taken looking north-east at rear of 25 Jaylo Place.

